Qty:

52 Um:

Each

: SUPPORT GUSSET (350) BASKET

: D2325

: N/A

: B

: D2325 REV B

: 02/05/2008

Date:

Tuesday, 22/04/2008 3:52:54 PM

User:

Julie Lecocq

## **Process Sheet**

**Drawing Name** 

**Part Number** 

Material

**Due Date** 

KJ/RF

**Drawing Number** 

**Project Number** 

**Drawing Revision** 

Customer

: CU-DAR001 Dart Helicopters Services

S.O. No. :

Type

Job Number **Estimate Number** 

: 38741 : 10496

P.O. Number

This Issue

: 22/04/2008

: NC

: 11 First Issue

: 37447 **Previous Run** 

Written By

Prsht Rev.

Checked & Approved By

Comment

02.12.06

Reformat; Rev B EC

: SMALL /MED FAB

E06.05.03 Water jet Est.

**Additional Product** 

Job Number:



Seq. #:

Machine Or Operation:

Description:

304/316 .063 Sheet

1.0

M304S16GA

Comment: Qty.: 304/316 SS .063 Sheet

Total: 25.3890 sf(s) 0.4883 sf(s)/Unit

10777 Batch: FLOW WATER JET

2.0

WATER JET



Comment: FLOW WATER JET

1-Cut as per Dwg D2325 Dwg Rev:

Prog Rev:\_


IR 8-4-24

2-Deburr if necessary

3.0

QC2





INSPECT PARTS AS THEY COME OFF MACHINE

Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

QC8

SECOND CHECK



Comment: SECOND CHECK

5.0

QC5

INSPECT WORK TO CURRENT STEP

Comment: INSPECT WORK TO CURRENT STEP



Page 1

Dart Ae	rospace L	td								
W/O:		WORK ORDER CHANGES						÷		
DATE	STEP	PROCEDURE CHANGE By				Date	te Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
			·					<del></del>		
	,									
				0						
Part No:		PAR #:	Fault Category:	NCR:	Yes N	o DQ	<b>A</b> :	_ Date: _		
	•				QA: N/C	Closed	d:	_ Date:		
NCR:		2	WORK ORDER NON-CO	NFORMANCE	(NCR)				····	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
DATE		<b>Description of NC</b> Section A	T	Corrective Action Section B	Vifi4i					
	STEP		Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector		
						:				
						!		÷		
							1			
							1			

NOTE: Date & initial all entries

Date:

Tuesday, 22/04/2008 3:52:54 PM

User:

Julie Lecocq

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SUPPORT GUSSET (350) BASKET

Job Number: 38741

Part Number: D2325

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

6.0

PACKAGING 1

PACKAGING RESOURCE #1





Identify and Stock Location:

0



7.0

QC21

FINAL INSPECTION/W/O RELEASE



08/04/28

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



MF 08-04-25

Dart Ae	rospace L	td							
W/O:			V	ORK ORDER CHANGES				7	
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								***	
								1	
								ı	
Part No:		PAR #:	Fault Ca	tegory:N	CR: Yes	No DQ	A:	Date:	
					QA: N	N/C Close	d:	Date: _	
NCR:			WORK OR	DER NON-CONFORMANC	E (NCI	₹)		,	
DATE	STEP Description of NC		Corrective Action Section B		0:	Verification		Approval	Approval
DAIL	O12	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Section C	ion C	Chief Eng	QC Inspector	
								- 1 2	
						-			

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	38741
Description: Support Gusset	Part Number:	D2325
Inspection Dwg: D2325 Rev: B		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST									
(E)		X First A	rticle [	Prof	totype				
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method o		mments		
Ø0.257	+0.006/-0.001	.)८५	*						
1.000	+/-0.010	1.008	XŁ						
0.500	+/-0.010	.5∞	*						
4.382	+/-0.010	4-381	*						
10.915	+/-0.010	10.915	*						
1.569	+/-0.010	1.568	×						
							*		
						4			
	+								
n									
	3								
							4		
		-							
	1,								
	•	1							
Measured by:	rB	Audited by	y: 5		Prototype	Approval:	N/A		
Date:	8-4-24	Date	Date: Odu(24			Date:			
Rev Date	Change					Revised by	Approv <b>∉</b> d		
A 06.05.08	New Issue			,		K 1/ 11 M	- (///		

